

MOX Systems - documentació tècnica

assembly-manual-visio-en.pdf

Traducció tècnica: consultar els dibuixos originals i pàgines de referència per a les dimensions.


Pàgina d'origen 1

GUIA DE MUNTATGE Visio


- 1 Trieu el perfil correcte segons el gruix del sòl.
- 2 Apliqueu la junta i col·loqueu l'ancoratge dels perfils en conseqüència.
- 3 Premeu el perfil fins que quedi fixat a la junta.
- 4 Col·loqueu la catifa al perfil.
- 5 Perfils de tall de 45 graus per a cantonades exteriors.
- 6 Alineeu els perfils a les cantonades externes i col·loqueu-los a la junta.
- 7 Col·loqueu la catifa al perfil.
- 8 Perfils de tall de 45 graus per a cantonades internes.
- 9 Alineeu els perfils a les cantonades internes i col·loqueu-los a la junta.
- 10 Col·loqueu la catifa al perfil. 6 8

Pàgina 1/1


Dibuixos originals i pàgines de referència




1 Pick the correct profile according to the flooring thickness.




2 Apply joint and place the profiles anchor accordingly.




3 Press the profile until it is fixed to the joint.




4 Place the carpet to the profile.




5 Cut profiles 45 degrees for external corners.




6 Align the profiles at the external corners and place them into the joint.




7 Place the carpet to the profile.



8 Cut profiles 45 degrees for internal corners.



9 Align the profiles at the internal corners and place them into the joint.



10 Place the carpet to the profile.