

Sistemas MOX - documentação técnica

assembly-manual-visio-en.pdf

Tradução técnica: consulte os desenhos originais e as páginas de referência para as dimensões.


Página de origem 1

GUIA DE MONTAGEM DO Visio


- 1 Escolha o perfil correto de acordo com a espessura do pavimento.
- 2 Aplique a junta e coloque a âncora dos perfis em conformidade.
- 3 Pressione o perfil até o fixar à junta.
- 4 Coloque o tapete no perfil.
- 5 Corte os perfis a 45 graus para cantos exteriores.
- 6 Alinhe os perfis nos cantos exteriores e coloque-os na junta.
- 7 Coloque o tapete no perfil.
- 8 Corte perfis a 45 graus para cantos interiores.
- 9 Alinhe os perfis nos cantos interiores e coloque-os na junta.
- 10 Coloque o tapete no perfil. 6 8

Página 1/1


Desenhos originais e páginas de referência




1 Pick the correct profile according to the flooring thickness.




2 Apply joint and place the profiles anchor accordingly.




3 Press the profile until it is fixed to the joint.




4 Place the carpet to the profile.




5 Cut profiles 45 degrees for external corners.




6 Align the profiles at the external corners and place them into the joint.




7 Place the carpet to the profile.



8 Cut profiles 45 degrees for internal corners.



9 Align the profiles at the internal corners and place them into the joint.



10 Place the carpet to the profile.